



HEWLETT PACKARD (HP) FLEXFABRIC SWITCH STIG REVISION HISTORY

24 July 2020

Developed by DISA for the DoD

| REVISION HISTORY | | | | | |
|--------------------|---|--|------------------|--|--|
| Revision Number | Document Revised | Description of Change | Release Date | | |
| V1R4 | - HP FlexFabric Switch L2S STIG, V1R2 | L2S: - V-66053, V-66083 - Removed requirement. | 24 July 2020 | | |
| | - HP FlexFabric Switch NDM STIG, V1R2 | NDM: - V-66169, V-66197, V-66239 - Removed requirements. | | | |
| | - HP FlexFabric Switch RTR STIG, V1R1 | RTR: - V-66105 - Removed requirement V-66123 - Mapped to SRG-NET-000362-RTR-000110 V-66125 - Mapped to SRG-NET-000512-RTR-000012. | | | |
| V1R3 | - HP FlexFabric Switch NDM STIG, V1R1 | NDM: - V-66241 - Corrected check content. The following STIGs were not updated this release: - HP FlexFabric Switch L2S STIG, V1R2 - HP FlexFabric Switch RTR STIG, V1R1 | 25 October 2019 | | |
| V1R2 | - HP FlexFabric Switch L2S STIG, V1R1 | L2S: - Removed HFFS-L2-000004 requirement. The following STIGs were not updated this release: - HP FlexFabric Switch NDM STIG, V1R1 - HP FlexFabric Switch RTR STIG, V1R1 | 25 January 2019 | | |
| V1R1 | - HP FlexFabric Switch L2S STIG | - Initial Release. | 09 March 2016 | | |
| V1R1 | - HP FlexFabric Switch NDM STIG | - Initial Release. | 26 February 2016 | | |
| V1R1 | - HP FlexFabric | - Initial Release. | 26 February 2016 | | |

| REVISION HISTORY | | | | | |
|--------------------|---------------------|-----------------------|--------------|--|--|
| Revision Number | Document Revised | Description of Change | Release Date | | |
| | Switch RTR STIG | | | | |