

UNCLASSIFIED



## **F5 BIG-IP 11.x STIG REVISION HISTORY**

**23 October 2020**

**Developed by DISA for the DoD**

UNCLASSIFIED

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
V2R1	<ul style="list-style-type: none"> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> <li>- F5 BIG-IP Device Management STIG, V1R7</li> <li>- F5 BIG-IP Local Traffic Manager, V1R4</li> </ul>	<p>- DISA migrated the F5 BIG-IP STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number to V2R1.</p> <p><b>Access Policy Manager:</b></p> <ul style="list-style-type: none"> <li>- F5BI-AP-000147 - Changed Parent SRG to SRG-NET-000517-ALG-000006, CCI-002361.</li> <li>- F5BI-AP-000151 - Changed Parent SRG to SRG-NET-000519-ALG-000008, CCI-002364.</li> <li>- F5BI-AP-000197, F5BI-AP-000199, F5BI-AP-000205, F5BI-AP-000207, F5BI-AP-000209 - Removed requirement; it is no longer in the parent SRG.</li> </ul> <p><b>Device Management:</b></p> <ul style="list-style-type: none"> <li>- F5BI-DM-000290 - Added a policy to APM stating if F5 is being used to authenticate users for web applications, the HTTP_Only flag must be set.</li> </ul> <p><b>Local Traffic Manager:</b></p> <ul style="list-style-type: none"> <li>- F5BI-LT-000139 - Changed Parent SRG to SRG-NET-000521-ALG-000002, CCI-001494.</li> <li>- F5BI-LT-000141 - Changed Parent SRG to SRG-NET-000514-ALG-000514, CCI-000057.</li> <li>- F5BI-LT-000143 - Changed Parent SRG to SRG-NET-000515-ALG-000515, CCI-000058.</li> <li>- F5BI-LT-000147 - Changed Parent SRG to SRG-NET-000517-ALG-000006, CCI-002361.</li> <li>- F5BI-LT-000151 - Changed Parent SRG to SRG-NET-000519-ALG-000008, CCI-002364.</li> </ul>	23 October 2020

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
		<p>- F5BI-LT-000197, F5BI-LT-000199, F5BI-LT-000205, F5BI-LT-000207, F5BI-LT-000209 - Removed requirement; it is no longer in the parent SRG.</p> <p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> </ul>	
V1R4	- F5 BIG-IP Local Traffic Manager, V1R3	<p><b>Local Traffic Manager:</b></p> <ul style="list-style-type: none"> <li>- V-60273 - Rule title updated to reference 800-52 Revision 2, which has superseded Revision 1.</li> <li>- V-60319 - Removed from STIG and placed in DNM status. Application does not provide session lockout function. Current Fix does not address the requirement to lock the session.</li> </ul> <p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP Device Management STIG, V1R7</li> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> </ul>	24 July 2020
V1R7	- F5 BIG-IP Device Management STIG, V1R6	<p><b>Device Management:</b></p> <ul style="list-style-type: none"> <li>- V-60091- Change check and fix procedures to require a Set the MaxClients = 10 (or less) to fix the mismatch with the actual requirement.</li> </ul> <p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP LTM STIG, V1R3</li> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> </ul>	24 January 2020

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
		<ul style="list-style-type: none"> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> </ul>	
V1R6	<ul style="list-style-type: none"> <li>- F5 BIG-IP Device Management STIG, V1R5</li> <li>- F5 BIG-IP LTM STIG, V1R2</li> </ul>	<p><b>Device Management:</b></p> <ul style="list-style-type: none"> <li>- V-97729 - Added new requirement.</li> <li>- Updated overview for clarification.</li> </ul> <p><b>Local Traffic Manager:</b></p> <ul style="list-style-type: none"> <li>- V-60311 - Set a TCP profile 'idle-timeout' set to 600/900 seconds would be more accurate to meet the requirement.</li> </ul> <p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> </ul>	25 October 2019
V1R5	- F5 BIG-IP Device Management STIG, V1R4	<p><b>Device Management:</b></p> <ul style="list-style-type: none"> <li>- F5BI-DM-000133 - Corrected Check Content; changed “Verify ‘SSL’ is configured...” to “Verify ‘Encryption’ is configured...”.</li> </ul> <p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP LTM STIG, V1R2</li> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> </ul>	28 July 2017
V1R4	- F5 BIG-IP Device Management STIG, V1R3	<p><b>Device Management:</b></p> <ul style="list-style-type: none"> <li>- F5BI-DM-000007 - Changed requirement from 900 Seconds (15 minutes) to 600 seconds (10 minutes) to coincide with the setting in F5BI-DM-000137.</li> </ul>	28 April 2017

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
		<p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP LTM STIG, V1R2</li> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> </ul>	
V1R3	<ul style="list-style-type: none"> <li>- F5 BIG-IP Device Management STIG, V1R2</li> <li>- F5 Big-IP LTM STIG, V1R1</li> <li>- F5 BIG-IP Device Management STIG Overview</li> </ul>	<p><b>Device Management:</b></p> <ul style="list-style-type: none"> <li>- F5BI-DM-000041 - Removed check from STIG as inherently meets.</li> </ul> <p><b>Local Traffic Manager:</b></p> <ul style="list-style-type: none"> <li>- F5BI-LT-000203 - Updated Check Content and Fix Text Sections.</li> <li>- F5BI-LT-000057, F5BI-LT-000059, F5BI-LT-000061, F5BI-LT-000063, F5BI-LT-000065; Updated Vulnerability Discussion, Check Content, and Fix Text sections.</li> </ul> <p><b>Overview:</b></p> <ul style="list-style-type: none"> <li>- Added Section 1.8 Product Approval Disclaimer.</li> </ul> <p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> </ul>	28 October 2016
V1R2	<ul style="list-style-type: none"> <li>- F5 BIG-IP Device Management STIG, V1R1</li> </ul>	<p><b>Device Management:</b></p> <ul style="list-style-type: none"> <li>- STIG V-60155 updated Rule Title, Check Content, and Fix Text to require only eight (8) characters be changed instead of 15 when changing a password.</li> </ul>	23 October 2015

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
	- F5 BIG-IP Device Management STIG Overview	<p>- STIG V-60137 updated Rule Title, Check Content, and Fix Text to require the use of NIAP evaluated cryptographic mechanisms.</p> <p><b>Overview:</b></p> <p>- Overview updated Other Considerations Section.</p> <p><b>The following STIGs were not updated this release:</b></p> <ul style="list-style-type: none"> <li>- F5 BIG-IP Access Policy Manager STIG, V1R1</li> <li>- F5 BIG-IP Advanced Firewall Manager, V1R1</li> <li>- F5 BIG-IP Application Security Manager, V1R1</li> <li>- F5 BIG-IP LTM STIG, V1R1</li> </ul>	
V1R1	- N/A	- Initial Release.	29 May 2015